J6 WIRING DIAGRAM 13 (WT)